





RATING: 350 A CO2 250A MIXED GAS @ 100% DUTY CYCLE .30" 0.8MM TO .062" 1.6MM WIRE

Parts Manual


MIG Gun Part Numbering System

Bernard EZ Feed II 350 Amp





No.	Part No.	Description				No.				
1	4491 4492 4591 4592	Nozzle- Brass 3/4" Nozzle- Brass 9/16" Nozzle- Copper 3/4" Nozzle- Copper 9/16"	I.D. BND I.D. BND I.D. BND I.D. BND	350A 350A		2	7488 7498 7490 7491 7496 7497 7498	Contact Tip Contact Tip Contact Tip Contact Tip Contact Tip Contact Tip Contact Tip	.030" .035" .045" .063" .040" .023" .052"	0.8mm 0.9mm 1.2mm 1.6mm 1.0mm 0.6mm 1.4mm
	Wire Size	Length	Parts No.	Wire	Wire Size		Length		Parts No.	
3	.023030 .023030 .023030 .035045 3/64" AI .035045 1/16" .035045 .035045 1/16" 1/16"	10' 15' 10' 15' 15' 25' 15' 10' 15' 25' 10' 15'	43010 43015 43110 43115 43115 43125 43215 44110 44115 44125 44210 44215 44225T	1/1 5/6 5/6 3/3 3/3 7/6 7/6	64" 64" 62" 64" 64" 504 6"		2 1 1 1 1 1 1	5' 25' 5' 0' 5' 5' 5' 5' 5'	44215 44225 44310 44315 45615 45615 45615 44115 44215	5 5 6 7 6 7 7 7 7



- 1. Disconnect all power before servicing or changing welding gun components. Failure to disconnect power can lead to dangerous electrical shock which can kill.
- 2. Smoke, fumes and gases can be dangerous to your health. Keep smoke, fumes and gases from the breathing area. Fumes from welding are of various types and strengths, depending on the kind of base metal being welded.
- 3. Arc welding produces dangerous light radiation. Adequate eye protection must be worn.
- 4. All exposed skin must be covered with flame resistant, protective clothing. Do not wear clothing made from flammable synthetic fibers.
- 5. Protective screens or barriers should be used to protect others from spatter, flash and glare while welding.

TROUBLESHOOTING

1. Poor Wire Feed

- Conduit liner clogged or kinked
- · Incorrect liner size or contact tip
- Line cut too short and not seating properly in gas diffuser
- Drive rolls too tight resulting in scoring of welding wire
- · Welding wire dirty, rusty and/or too much cast

2. Short Tip Life

- Drive rolls too tight resulting in scoring of the welding wire
- · Welding wire dirty, rusty and/or too much cast
- Uncoated wire being used, increasing usage
- · Wrong tip size
- Over torch rated duty cycle
- Loose contact tip and/or retaining head

3. Gun Overheating

- · Loose retaining screw on quick connect block
- Insufficient gauge power cable and/or ground cable
- Loose connector cone and/or cone nut
- Gun being run beyond its amperage range
- Electrical malfunction in power source

4. Switch Malfunctioning

- Bad connection of leads to switch terminals
- Spatter built up between lever and switch housing
- · Contacts dirty in switch
- Switch housing screws loose
- Broken or worn switch lead

5. Weld Porosity

- Spatter built up in nozzle blocking gas
- Leaks in gas hose or improper connection
- O-rings on power pin are cut or damaged
- Inner tube loose from connector cone
- Improper shielding gas or welding wire
- · Rusty or poor quality welding wire
- Parent metal rusty or contaminated or high in Sulfur content
- Flow improperly set

6. Contact Tip Burn Back

- Improper voltage and/or wire feed speed
- Erratic wire feeding
- Improper tip stick-out
- Improper electrode stick-out
- Faulty ground

7. Erratic Arc

- · Worn contact tip
- Buildup inside of line
- Wrong tip size
- Not enough bend in neck

8. Extreme Spatter

- Improper machine parameters
- Improper tip installation
- Improper tip shielding
- Contaminated wire or work piece

CONTACT US

AMERICAN TORCH TIP CO. 800.342.8477 941.753.7557 FAX: 941.753.6917 Sales@attcusa.com AmericanTorchTip.com

The AIGHTNING Family of MIG Guns



Large Curve MIG Gun



Robotic MIG Gun



Small Curve MIG Gun



Semi-Auto MIG Gun



Automatic MIG Gun